PAYLOAD FLIGHT HAZARD REPORT				a. NO:	AMS-	02-F18	
b. PAYLOAD	Alpha Magnetic S	Alpha Magnetic Spectrometer-02 (AMS-02)		c. PHA	ASE:	II	
d. SUBSYSTEM	M: All	e. HAZARD GRO	Loss of Orbite ISS	er, Loss of f. DAT	E: May 2	2, 2006	
g. HAZARD TITLE: Rapid Safing/Payload Reconfiguration				i. HAZ	ARD CATASTI	ROPHIC	X
g. HAZARD TI	Rapid Samigrayi	load Reconfiguration	guration		GORY: CR	RITICAL	
h. APPLICABL	E SAFETY REQUIREMENTS:	NSTS 1700.7B and	ISS Addendum, 202	.4a, 202.4b, 202.4c (	(ISS only), 205		
j. DESCRIPTIO	ON OF HAZARD:		ude: Inability to close orbit boost or inabilit				
k. CAUSES							
	1 D 1 L 1	CD 1 1D D /01:	. D				
		f Payload Bay Doors/Orbi					
	2. Configuration prec	cludes ISS Operation such	as reboost/EVA				
(list)	<ul><li>2. Configuration prec</li><li>3. AMS-02 Reconfig</li></ul>	•	as reboost/EVA rn				
(list)	<ul><li>2. Configuration prec</li><li>3. AMS-02 Reconfig</li></ul>	cludes ISS Operation such uration precludes safe retu	as reboost/EVA rn				
(list)	<ul><li>2. Configuration prec</li><li>3. AMS-02 Reconfig</li></ul>	cludes ISS Operation such uration precludes safe retu	as reboost/EVA rn ervice Loss		SSP/ISS		
(list)	<ol> <li>Configuration pred</li> <li>AMS-02 Reconfig</li> <li>Configuration requ</li> </ol>	cludes ISS Operation such uration precludes safe retu nirement for planned ISS S	as reboost/EVA rn ervice Loss		SSP/ISS		
(list)	<ol> <li>Configuration prec</li> <li>AMS-02 Reconfig</li> <li>Configuration requ</li> <li>APPROVAL</li> </ol>	cludes ISS Operation such uration precludes safe retu nirement for planned ISS S	as reboost/EVA rn ervice Loss		SSP/ISS		

PAYLOAD FLIGHT HAZARD REPORT	a. NO:	AMS-02	2-F18
b. PAYLOAD Alpha Magnetic Spectrometer-02 (AMS-02)	c. PHASE:	II	
1. HAZARD CONTROL (CONTROL), m. SAFETY VERIFICATION METHODS (SVM), n. STATUS OF VERIFICATIONS (STATUS)			OPS CONTROL
1. CAUSE: Preclude closure of Payload Bay Doors/Orbiter Return			
1.1 CONTROL: The AMS-02 design does not contain any mechanisms or structures that protr payload bay door dynamic envelop. Payload bay doors can be closed without physical constra 1.1.1 SVM: Review of AMS-02 Design.			
1.1.2 SVM: Analysis of Dynamic Envelop intrusions.			
1.1.1 STATUS: Open. AMS-02 outer mold line model reviewed and all close clearance the process described in NSTS 37329 Appendix Q.	e points identifie	d through	
1.1.2 STATUS: Open. Close clearance points included in AMS-02 dynamic math mode results show no intrusions into dynamic envelope. Points will continue to be monitored			
1.2 CONTROL: The AMS-02 design does not require a specific configuration of AMS-02 system connection) to safely return to the ground. Note: Valves designated DV15(A-D) are required to element turnaround operations.			
1.2.1 SVM: Review of Design.			
1.2.1 STATUS: Open Cryosystem review of design for safe return configuration docur 4390-06-SP-MEMO-0004 dated 06 March 2006 from AMS-02 Chief Engineer Chris To		ESCG-	
1.3 CONTROL: The AMS-02 does not need any special thermal conditioning of composite str of the nominal mission profile to allow for safe return.	uctures or other	systems off	
1.3.1 SVM: Thermal Analysis to confirm thermal condition of structure under worst ca	se conditions.		
1.3.2 SVM: Structural Analysis to confirm adequate margin for thermal extremes of co	mposite structure	es/systems.	
1.3.1 STATUS: Open			
1.3.2 STATUS: Open			
1.5 CONTROL: The AMS-02 is safe to return only with all PRLAs and the Active Keel (latch rule will be in place that the AMS-02 can only return with this safe configuration. In the event closed either electrically or by EVA, the AMS-02 will have to be returned to be berthed upon t	that all latches of	cannot be	S

	PAYLOAD FLIGHT HAZARD REPORT	a. NO:	AMS-02-F18
b. PAYLOAD	Alpha Magnetic Spectrometer-02 (AMS-02)	c. PHASE:	II
working latche	es is available to return the vehicle.	-	
1.5.1 S	SVM: Structural Analysis to verify safe return with 4 of 4 PRLA and Keel 1	Latch.	
1.5.2 S	SVM: Review of Flight Rules.		
1.5.1 S	STATUS: Open		
1.5.2 S	STATUS: Open		
2.0 CAUSE: (	Configuration precludes ISS Operation such as reboost/EVA		
	L: The AMS-02 does not reconfigure its elements in such a manner that reandle worst-case ISS loads. (NOTE: The ability to sustain ISS/Orbiter loads)		
2.1.1 S	SVM: Review of design.		
2.1.2 S	SVM: AMS-02 Structural Analysis.		
2.1.1 S	STATUS: Open		
2.1.2 S	STATUS: Open		
EVA crew downagnet be disc (Note this is sp	L: The AMS-02, whether operating with a charged magnet or uncharged, of which truss past the AMS-02. For any EVA that involves the AMS-02 directorage, however would not be a time critical event and the time to discharge pecifically addressed in AMS-02-F07)	ectly will require that t	the AMS-02
	SVM: Review of design		
	SVM: Inspection of as built design		
	SVM: Magnetic Field Analysis		
	STATUS: Closed by MAGIK Analysis		
	STATUS: Open		
	STATUS: Open		
	STATUS: Open		

	PAYLOAD FLIGHT HAZARD REPORT	a. NO:	AMS-02-F18
b. PAYLOAD	Alpha Magnetic Spectrometer-02 (AMS-02)	c. PHASE:	II
PAS site on th	e ISS Truss without specific reconfiguration of the AMS-02 hardware or avionics.	•	
2.3.1 \$	SVM: Review of Design.		
2.3.2 \$	SVM: Fit Check of hardware (Shuttle).		
2.3.3 \$	SVM: Fit Check of hardware (ISS).		
2.3.1 \$	STATUS: Open		
	STATUS: Open. AMS will undergo a standard fit check to the Shuttle payload bay prior to launch. ISS Fit Check.	during ground	processing
	STATUS: Closed. Memo ESCG-4390-05-SP-MEMO-0012, "Functional Testing on" dated 28 December 2005, from AMS-02 Chief Engineer Chris Tutt.	f the Payload A	attach
3. CAUSE: A	MS-02 Reconfiguration precludes safe return		
ISS. Over lon	L: The AMS-02 does not alter its configuration to preclude return at the end of its g term operations of the AMS-02 the superfluid helium is consumed. The AMS-02 tity of superfluid helium, including entirely empty.		
3.1.1 \$	SVM: Structural Analysis to confirm insensitivity to pressure loading superfluid he	lium tank	
	STATUS: Open. AMS-02 currently showing positive margins to completely filled, urations for all landing events.	half-filled, and	empty
	L: The AMS-02 Pressure systems do not require pressure stabilization of any presincluding vacuum case and helium tank)	surized tanks o	r
3.2.1 \$	SVM: Review of Design.		
3.2.2 \$	SVM: Structural Verification Plan.		
3.2.1 STATUS: Open			
3.2.2 \$	STATUS: Open		
mechanism is the mechanism	L: In the contingency return of the AMS-02 in the event the EVA release of the P design to be reassembled by reversing the release procedure. Travel limits built in to the pre-released state and preload capability. NOTE: For Orbiter return, the this configuration to structurally survive loads or stay within the Orbiter payload.	to the mechanis mechanism doe	sms return s not need to

PAYLOAD FLIGHT HAZARD REPORT	a. NO:	AMS-02-F18
b. PAYLOAD Alpha Magnetic Spectrometer-02 (AMS-02)	c. PHASE:	II
however reinstallation will be requested to preserve operations of the hardware.	·	
3.3.1 SVM: Review of Design.		
3.3.2 SVM: Structural analysis to verify positive margins.		
<ul><li>3.3.1 STATUS: Closed. Memo ESCG-4390-06-SP-MEMO-0001, "Mechanical Desi System (PAS)", Dated 8 January, 2006 from AMS-02 Chief Engineer.</li><li>3.3.2 STATUS: Open</li></ul>	gn of the Payload	Attach
3.4 CONTROL: In the event the ROEU folding bracket is folded prior to a return in the Orb will maintain positive margins in both configurations.	iter, the ROEU fol	lding bracket
3.4.1 SVM: Structural Analysis of ROEU Folding Bracket.		
3.4.1 STATUS: Open		
4 CAUSE: Configuration requirement for planned ISS Service Loss		
4.1 CONTROL: The AMS-02 does not require any configuration changes to support planners afe configuration or condition of the AMS-02 hardware. The AMS-02 is designed to support of ISS Services without causing a hazard to the ISS, the crew or other payloads.  4.1.1 SVM: Review of Design  4.1.1 STATUS: Open		
Notes:		

P	•
$\overline{}$	١
$\propto$	
0	١
6	•

AMS-02 – Alpha Magnetic Spectrometer

DCLA – Design Coupled Loads Analysis

EVA – Extravehicular Activity

ACRONYMS

PAS – Payload Attach Site, Payload Attach System

ROEU – Remotely Operated Electrical Umbilical

49910	10070